


PARTS LIST FOR 1A & 2A GRINDING MILL



Description :-

1	Front	26	Flywheel
2	Box	27	Spanner
3	Brass Bearing with Ring	28	Grinding Plate
4	Bottom Hopper	29	Screws for Plate
5	Chair and Cap (Bearing Block)	30	Tin Hopper
6	Frame	31	Screen for shoe
7	Spindle Spring	32	Bush for Leg with Arm
8	Collar	33	Jigger Spring
9	Cam	34	Jigger Rod
10	Driving Plate	35	Regulating wheel screw rod
11	Leg with Arm	36	Spring for front
12	Leg	37	Stud for front
13	Top Hopper	38	3/8 sq. key
14	Shoe	39	7/16 sq. key
14a	Shoe Pin	40	Thrust Block
15	Shoe Link	41	Toe for spindle
16	Leg Bearing	42	Spindle Nut
17	Jigger	43	Spindle
18	Shaking Lever	44	Shoe Spring
19	Feed regulating Nut	45	Rod-bridge-feed regulating Nut
20	Bridge	46	Rod bridge to Shoe
21	Click Holder	47	Click Holder Pin
22	Click	48	Stud for Chair & Cap
23	Drip Dish	49	Rod-shoe to shoe link
24	Regulating Wheel	50	Brace for Leg (Sheet)
25	Driving Pulley	51	Brace for Leg (Long)
		52	Leg and Foot